



FIRE EMT

Emergency Management Training




SAFETY NOTICE 3

International Terminal Common User Self Service Project Level 4 CUSS hoarding adjustment affecting egress route

The following essential information must be passed to all ITB tenants and stakeholders who are to make themselves aware of these changes in particular Level 4 staff.

As part of the International Terminal Common User Self Service (CUSS) project requires ceiling rectification works on Level 4 and in line with BAC Stakeholder Notice: [I-131 Level 4 CUSS hoarding adjustment](#).


From Friday 7th November the emergency egress route on the Northern side of Level 4 will change direction in the area marked by the blue circle below.



If evacuation is required to landside, towards the goods lift and northern service corridor (Zone 16), egress can be made via the new pathway indicated by the solid green line above.



If a secondary evacuation route is required from the goods lift area and the main exit stairwell is impeded, emergency egress can be made via the new passageway to the check in hall (indicated by blue circle below) and out to Assembly Area A4.



Wardens in Zone 16, as well as all staff working in these areas, are to familiarise themselves with these temporary amendments.

Evacuation Diagrams in the area have been amended to reflect this change.

Please contact me via email with any questions regarding these changes throughout the project.

Garry Dawson (GiFireE) BAC Fire Safety Advisor
Mob: 07 5428 1843 Ext 4
Email: garry.dawson@fireemt.com.au